

<b>Creek Bank</b>	<b>u/s End Station (ft)</b>	<b>d/s End Station (ft)</b>	<b>FP Length (ft)</b>	<b>FP Height (ft)</b>	<b>Floodplain unit description</b>
SA CK RB	44,279	44,008	271	3-4	Existing residential garden; Recent fine sed dep; Dec-31-05 HWM = WSE + 4.5 ft
SA CK LB	42,705	42,630	75	3-4	Alluvial banks
SA CK LB	40,674	40,613	61	5	
SA CK LB	39,570	39,505	65	4	
SA CK LB	39,094	38,990	104	4	
SA CK LB	38,489	38,407	81	5	Existing vegetation dominated by blackberry ( <i>Rhus</i> ); Potential riparian canopy and terrestrial habitat enhancement site
SA CK LB	37,740	37,558	182	6	Lt class RR bank along fp
SA CK LB	37,295	37,102	194	7	Potential riparian canopy and terrestrial habitat enhancement site
SA CK LB	37,042	36,789	253	5	
SA CK LB	36,708	36,560	149	8	
SA CK RB	36,565	36,353	212	7-8	Densely vegetated; increases to 10-ft height at d/s end
SA CK LB	36,560	36,291	269	5	
SA CK LB	36,452	36,171	281	7	
SA CK LB	36,072	35,915	157	7	
SA CK RB	35,741	35,624	117	6-7	Residential development; Existing RR bank along length of fp; Recommended fp enhancement site
SA CK LB	35,488	35,388	100	6	
SA CK LB	35,101	35,031	70	6	
SA CK LB	34,943	34,884	59	6	
SA CK LB	33,902	33,789	112	6	
SA CK RB	33,681	33,617	64	4	
SA CK LB	33,675	33,524	151	7	
SA CK LB	33,041	32,747	294	3-4	
SA CK LB	31,128	30,960	168	8	
FX CK LB	9,400	9,327	73	3-4	Floodplain unit on White Hill School property; Recent vegetation enhancement at site; Continues u/s from Town of Fairfax limits
FX CK LB	8,256	8,175	81	6	
FX CK LB	7,767	7,722	45	4	
FX CK LB	7,606	7,428	177	6-7	
FX CK RB	7,430	7,248	182	5-5.5	HWM on chain-link fence at TOB; Adj residential site appears flooded 12-31-05
FX CK LB	7,321	6,811	509	6	
FX CK RB	7,079	6,948	131	3-4	"Poster child" Fairfax Ck floodplain unit; Example for fp construction and enhancement projects; Numerous mature alders and low roughness understory; fine sed cap; Note: however non-native groundcover dominates understory; Floodplain appears approx. 45 ft-wide at Station 6,945 ft
FX CK LB	6,556	6,353	203	6	
FX CK RB	4,244	4,212	32	3-4	Recommended canopy enhancement site
FX CK RB	1,671	1,637	34	6-7	High sand covered gr bar; Sand dep may be caused by backwater effect of undersized Merwin Ave culvert