



TOWN OF FAIRFAX

STAFF REPORT

September 7, 2016

TO: Mayor and Town Council

FROM: Garrett Toy, Town Manager *GT*

SUBJECT: Approve permanent bike rack installation on the corner of Broadway and Bolinas

RECOMMENDATION

Approve permanent bike rack installation on the corner of Broadway and Bolinas

DISCUSSION

In November 2014, the Council approved the installation of a temporary metal bike rack at the corner of Broadway and Bolinas Road. The intent was to provide a safe location for bike storage so that bicycles would not be stored on the sidewalk, creating an obstacle for pedestrians. As part of the installation, the parking space adjacent to the bike racks was converted into a commercial yellow loading zone.

Staff provided Council with status reports on the bike rack usage at its January and June 2015 meetings. In December 2015, the Council approved the replacement of the temporary bicycle racks at Broadway and Bolinas with permanent bicycle racks.

The current location is approximately 10 ft. by 23 ft. For a permanent rack installation, the owners of the Coffee Roastery would like to install 4 campus-style double-sided bike racks (see attached) that can accommodate a total of 32 bikes (bike slots) and install 2 planter boxes. Under this scenario, we would retain the existing delineators and paint a solid white line around the corral. The Coffee Roastery has committed to pay for half the cost of the racks, and to purchase, install, and maintain the planter boxes. Unfortunately, the Bay Area Air Quality Management District's (BAAQMD) bike rack voucher program is not available until next year. However, we can purchase the racks at the BAAQMD negotiated price. The quoted price for 4 red powdered-coated bike racks, including tax, delivery and installation hardware, ranges from \$2,791-\$2,966 depending on whether the delivery can be bundled with other deliveries.

FISCAL IMPACT


The Town would pay for 50% of the cost (up to \$1,500) for the purchase and delivery of the racks. Staff would install the racks and remove the temporary rack. The improvements would be charged to CIP Fund 53-804 (Sidewalk Repair).

ATTACHMENTS

Picture of type of bike rack (BAAQMD pricing is only for galvanized racks)
Rough layout

AGENDA ITEM # 4

Campus-style double-sided bike rack (8 bikes/rack)





B & B STEEL & SUPPLY OF SANTA MARIA

STEEL • PIPE • ALUMINUM • STAINLESS STEEL • WIRE • SURPLUS PRODUCTS

1233 Furukawa Way

Santa Maria, CA 93458-4929

805-349-9991

800-350-5959

FAX 805-349-8498

www.bbmetals.com


Date: _____

Customer: Fairfax - 32 SLOTS

Quotation: Order #: _____

Contact: _____

Phone: _____



Total space used is 23' 3". You can leave 4" space between racks to get to 23.0'.

Dimensions: OD _____ ID _____

By: _____

ATTACHMENT 2